

INSTALLATION INSTRUCTIONS





TOOL LIST:
3/16 HEX WRENCH (PROVIDED)

ASSEMBLY STEPS:

- 1. SLIDE THE **PRINTER TRAY & ARM ASSEMBLY** ONTO THE CUSTOMER'S POLE THEN TIGHTEN THE 2X 1/4-20 SOCKET SCREWS TO SECURE AT DESIRED HEIGHT.
- 2. PLACE PRINTER ONTO THE **PRINTER TRAY**.
- 3. ROUTE **Printer Cables** through **2x cable clips** as shown.

	AR	RELEASED FOR PROTOTYPE			09/24/14	JVT	CDB	
	REV.	DESCRIPTION			DATE	BY	CHK'D	
DIMS. AND TOLERANCES PER ASME Y14.5 - 1994	DRAWN	J. TERVEER						
UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES	DATE 09/24/2014							
TOLERANCES ARE:	CHECKED							
FRACTIONAL ± 1/32	DATE		CUSTOMER INSTALLATION,					
2 PLC. DEC. ± .03	DO NO	DO NOT SCALE DRAWING		PRINTER TRAY WITH ARM,				
3 PLC, DEC. ± .010	MATERIAL		FIXED CLAMP, FOR \emptyset 2.00 POLE					
	SEE B.	.O.M.	SIZE D	DWG. NO.	7 21 / 1	RE	. A	
ANGULAR ± 0°30'	FINISH	N/A	D 36		7-3161	SH	HEET 1 OF 1	

THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF