



TOOLS LIST:  
1. 3MM HEX WRENCH OR BIT WITH DRIVER  
2. #1 PHILLIPS SCREW DRIVER

## COUNTER ATTACHMENT






ASSEMBLY STEPS:  
1. ATTACH SC-1000-CF TO COUNTER THROUGH 4X COUNTER SINK HOLES.  
(CUSTOMER TO PROVIDE ATTACHMENT SCREWS)



### DETAIL A

## DISPLAY INSTALL & PRINTER INSTALL



ASSEMBLY STEPS:  
1. LOOSEN 2X SET SCREWS.  
2. HOLD DISPLAY ATTACHMENT BRACKET AT DESIRED HEIGHT.  
3. TIGHTEN 2X SET SCREWS.  
4. ATTACH DISPLAY WITH 4X M4 X 10MM LONG PHILLIPS SCREWS.  
5. SLIDE PRINTER BRACKET TO DESIRED LOCATION.  
6. PLACE PRINTER INTO SC-1000-CF UNIT. 4X SCREWS CAN BE LOOSENED TO ADJUST PRINTER BRACKET (SEE DETAIL A).  
(**OPTIONAL**) DUAL LOCK (2 STRIPS INCLUDED) CAN BE USED UNDER THE PRINTER TO HOLD IT IN PLACE IF DESIRED.

DWG. NO.  
SC-1000-CF

REV.  
C

TITLE

SC-1000,  
SELF CHECK-OUT,COUNTER TOP,  
FIXED BASE

DRAWN  
S. YANG

DATE  
3/27/2023

SHEET 1 OF 1

HAVIS

THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF HAVIS, INC. AND REPRODUCTION IN PART OR IN WHOLE WITHOUT THE WRITTEN PERMISSION OF HAVIS, INC. IS PROHIBITED.

## CUSTOMER INSTRUCTIONS