

## TECHNICAL SERVICE BULLETIN

**Subject:** Seat Mount Bolts

**Vehicle:** 2007 Dodge Charger

**Issue:** The 2006 Charger was introduced with sensors that cause the vehicle ( OEM ) computer to be recalibrated by an authorized Dealership if seat bolts are removed and replaced. Dodge does not recommend that the seat bolts are used for mounting accessory brackets. Havis Shields does Not provide a C-TCB or Hump bracket for newer Dodge vehicles for this reason.

**Change:** Dodge adjusted the sensitivity of the seat bolt sensors on the 2007 Charger. If seat bolts are removed and replaced, recalibration is of OEM computer is Not required. Dodge still does not recommend that the seat bolts are used for mounting accessory brackets

**NOTE:** Havis Shields will continue Not to provide seat bolt mounting brackets for the 2007 Dodge vehicles.

\*\*\* Our current console and computer mount solutions for these vehicles have proven to be very successful and should meet the needs for most customers who are looking for a proper installation.

Havis-Shields is committed to quality workmanship and Technical Support. Please contact our team at 1.800.524.9900 with questions &/or comments.