
INSTALLATION INSTRUCTIONS

-DISPLAY MOUNT


2X SET SCREWS

TOOLS LIST:

- 1. 3MM HEX WRENCH OR BIT WITH DRIVER
- 2. 8MM SOCKET WITH DRIVER
- 3. #2 PHILLIPS SCREW DRIVER




1. LOOSEN 2 SET SCREWS AND REMOVE DISPLAY MOUNT




ASSEMBLY STEPS:

3. SLIDE DISPLAY MOUNT BACK INTO PLACE AND TIGHTEN SET SCREWS.



ASSEMBLY STEPS:

2. ATTACH PAYMENT ARM AND ATTACHMENT PLATE
TO SC UNIT WITH 2X WASHERS AND 2X LOCK NUTS.



ASSEMBLY STEPS:

- 4. LOOSEN 2X PHILLIPS SCREWS TO ADJUST ARM.
- 5. RE-TIGHTEN SCREWS TO SECURE ARM LENGTH.

DWG. NO.
SC-1000-ACC-03

DRAWN
S. YANG

REV.
C

DATE
3/27/2023

ATTACHMENT PLATE-

SELF CHECK-OUT ACCESSORY, PAYMENT ARM MOUNT, SC-1000

HEET I OF I

CUSTOMER INSTRUCTIONS

THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF HAVIS, INC. AND REPRODUCTION IN PART OR IN WHOLE WITHOUT THE WRITTEN PERMISSION OF HAVIS, INC. IS PROHIBITED.