



## HAVIS, INC MM-10-501 & MM-10-502 PRINTER MOUNT INSTALLATION



Tools Required: 2.5mm Hex Wrench (Provided)

**Step 1:** Attach the Printer Mount to the Arm using the M4 x 20mm Socket Head Screw as shown



